


HPA-0 10 C Premium







AIR SOURCE HEAT PUMPS

PRODUCT-NO.: 238979

Required accessories

Article	Part no.	Type	Description
	236000	<u>WPM international</u>	Heat pump manager in wall mounted enclosure

Recommended accessories

Article	Part no.	Type	Description
	233826	<u>HMS Trend</u>	Hydraulic module
	232805	<u>HM Trend</u>	Hydraulic module
	232964	<u>SK 1</u>	T-support
	234722	<u>WK 2</u>	Wall mounting bracket
	233622	<u>AS-WP 1</u>	Hydraulic connection set
	233623	<u>AS-WP 2</u>	Hydraulic connection set









229336


[**ISG web**](#)

Internet Service Gateway

DHW cylinder

Article	Part no.	Type	Description
	234801	HSBC 200 S	Integral cylinder
	221360	SBB 301 WP	DHW cylinder
	221361	SBB 302 WP	DHW cylinder
	229981	SBS 801 W	Instantaneous water cylinder
	233510	HSBC 200	Integral cylinder
	203801	HSBC 300 cool	Integral cylinder

Buffer cylinder

Article	Part no.	Type	Description
	185458	SBP 200 E	Buffer cylinder



220824

SBP 400 E

Buffer cylinder



203763

STH 210 Plus

Buffer cylinder



203764

STH 415 Plus

Buffer cylinder

Contact information

You have questions? We appreciate to help you:

Call +49 5531 - 7020

Write an email to info@stiebel-eltron.com

Installation information

Please ask your local power supply utility or a registered electrician to install appliances that are not fully wired, i.e. ready to plug in. The electrician should also be able to assist you with obtaining the agreement of the respective power supply utility required for the appliance installation.